Under Review Notification

Raised By: Vanessa Morel Product #: RB T101637-101

Date: 2019.10.30 Product Name: GRIP AND SPINDLE SLING ASSEMBLY

		"Y" or "N" Required for Each Part									
		Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RB T101637-101	RB T101637-101 Rev	Υ	Υ	Ν	Υ	Υ	N	N	N	19-1139	See below

Description of Issue:

Issues stated on ADR (Safety issue)

RB T101637-101 and items -103, -105, -107, -109, -111, -113 and -135 must be put on **HOLD** in Plex

RB T101637-101 Finish good stock must be put in quarantine

Items -103, -105, -107, -109, -111, -113 and -135

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of OperationsChief EngineerProduction EngineersProduct Manager - Solutions ProviderDirector Quality AssuranceEngineering Project ManagersProduction PlannersSupply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene